



THIEL Restoration Price List

All pricing is per speaker. Labor is \$125 per hour.

Model No.	Light sanding, respray with new topcoat	Full Service refinish including touch ups	Extreme Repairs	Add grille restretch black fabric (Add \$20 ea. for optional colors)	Replace outer cartons for return shipping.
01	\$300-\$350	\$375-\$500	\$500-\$625	\$80	
SCS				\$100	
02, SCS2, SCS3				\$40	
SCS4				N/A	
03, 03a, 04, 04a, CS.5	\$350-\$425	\$500-\$875	\$750+	\$40	
CS1, CS1.2, CS1.5,					
MCS1					
CS1.6, CS2, CS2.2,	\$300-\$375	\$625-\$1000	\$875+	\$40	
CS2.3, CS3, CS3.5,					
SmartSub SS1, SS2					
CS2.4, CS3.6, CS3.7,	\$425-\$500	\$875-1250	\$1125+	\$60	
CS5, CS6, CS7, CS7.2,					
SmartSub SS3					
SmartSub SS4	by Estimate Only				

Notes

- All speakers will have work estimated upon arrival. Please contact THIEL to discuss the level of service ordered at your request, or we will contact you as we see fit so that appropriate service is rendered.
- All speakers are tested for mechanical integrity and sonic performance.
- If any speaker is found to have silicone contamination from non-approved cleaners, add 2 hours for bookshelf through CS3 series, 3 hours for CS5-7 series. We can't know if contamination has occurred until work has already begun!
- Some speakers with a great degree of damage may look best if refinished as black-wood.
- Speakers built as recently as 1 year ago may have a higher sheen than what we currently use. Older speakers may have an even higher degree of sheen. We currently use matte finish lacquer for current production and all refinish orders.
- We no longer have original packaging for some models. Custom packaging will be fabricated for shipping and will be quoted as necessary or by request.
- Please contact us for driver rebuild pricing and availability. Estimate for mechanical repair will be provided upon arrival and full evaluation.